# Bulk Knot Wire Cup Brush

• For scale removal, deburring, weld cleaning and flat surfaces.

UPC#	SPEC	WIRE SIZE	ARBOR HOLE	MAX RPM	BOX QTY	
49645	2-3/4" Cup Knot Carbon	.014	5/8-11	12,500	10	Fast-Cut
49646	2-3/4" Cup Knot Carbon	.020	5/8-11	12,500	10	Fast-Cut
49647	4" Cup Knot Carbon 1 Row	.020	5/8-11	8,500	10	Fast-Cut

### **Bulk Crimped Wire Cup Brush**

• For light and medium duty cleaning including cleaning welds, burr removal and removing scale.

UPC#	SPEC	WIRE SIZE	ARBOR HOLE	MAX RPM	BOX QTY	
49648	2-3/4" Cup Brush Crimped Carbon Wire	.014	5/8-11	12,500	10	Fast-Cut

### Bulk Knot End Brush with 1/4" Shank

• Can be used at higher brushing speeds.

• For pipeline cleaning, CNC equipment maintenance/cleaning and removal of rust or scale.

UPC#	SPEC	WIRE SIZE	SHANK	MAX RPM	BOX QTY	
49649	3/4" Knotted End Brush Carbon with 1/4" Shank	.014	1/4" Shank	20,000	20	Fast-Cut
60133	1" Knotted End Brush Carbon with 1/4" Shank	.006	1/4" Shank	22,000	12	Made In USA
49650	1" Knotted End Brush Carbon with 1/4" Shank	.020	1/4" Shank	20,000	20	Fast-Cut

### Bulk Crimped End Brush with 1/4" shank

UPC#	SPEC	WIRE SIZE	SHANK	MAX RPM	BOX QTY	
60250	3/4" Crimped End Brush Carbon with 1/4" Shank	.010	1/4" Shank	22,000	100	Made In USA

#### Bulk Crimped Wire Wheel Brush with 1/4" Shank

UPC#	SPEC	WIRE SIZE	ARBOR HOLE	MAX RPM	BOX QTY	
49643	2" Crimped Carbon Wire with 1/4" Shank	.014	1/4" Shank	25,000	20	Fast-Cut
49644	3" Crimped Carbon Wire with 1/4" Shank	.014	1/4" Shank	25,000	20	Fast-Cut

# Bulk Copper Center Wheel Brush

• For general use including cleaning and rust removal.

UPC#	SPEC	WIRE SIZE	ARBOR HOLE	MAX RPM	BOX QTY	
49624	3" Crimped Brush	.008	1/2", 3/8" Adaptor	25,000	50	Fast-Cut