

MOUNTED POINTS

MOUNTED POINTS, DRESSING WHEELS, STICKS & HONES

Mounted Points Premium Pink Aluminum Oxide



- Used in almost every industry but primarily in tool and die shops, and foundries. General applications: Deburring, tool sharpening, finishing cavities, and removes mold marks and parting lines.
- Mounted points are classified by shape groups A, B, and W.
- The semi-friable pink PA abrasive is used to produce sharp, consistent cutting action.

A-Shape Mounted Points R.P.M.*

UPC#	SIZE	DIMENSION	SHANK	CARTON	UNIT
35951	A-1	7/8 x 2-1/2	1/4 Shank	10	20
35953	A-3	7/8 x 2-3/4	1/4 Shank	10	20
35954	A-4	1-1/4 x 1-1/4	1/4 Shank	10	20
35955	A-5	3/4 x 1-1/8	1/4 Shank	10	20
35957	A-11	7/8 x 2	1/4 Shank	10	20
35975	A-38	1 x 1	1/4 Shank	10	20

B-Shape Mounted Points R.P.M.*

UPC#	SIZE	DIMENSION	SHANK	CARTON	UNIT
35980	B-44	7/32 x 3/8	1/8 Shank	10	20
35985	B-52	3/8 x 3/4	1/8 Shank	10	20
36009	B-132	3/8 x 1/2	1/8 Shank	10	20

W-Shape Mounted Points R.P.M.*

UPC#	SIZE	DIMENSION	SHANK	CARTON	UNIT
36042	W-189	1/2 x 2	1/4 Shank	10	20
36058	W-220	1 x 1	1/4 Shank	10	20
36060	W-222	1 x 2	1/4 Shank	10	20
36067	W-236	1-1/2 x 1/2	1/4 Shank	10	20

* No matter what factors of wheel size, shape, specification, mandrel size, overhang, or machine conditions are changed, the speed of 10,000 SFPM shall not be exceeded.

Dressing Wheels, Sticks & Hones

- Combination Stone: Designed to clean magnetic chucks.
- Dressing Wheels: Break control devices used for dressing/opening diamond wheels.
- Dressing Sticks: Dressing and opening vitrified bonded wheels.
- Silicon Carbide



Dressing Wheels 10,823 R.P.M.

UPC#	SIZE	SPEC.	CARTON	UNIT
35905	3 x 1/2 x 1/2	72C-80-L-V	50	100
35906	3 x 1 x 1/2	72C-60-L-V	20	40
35907	3 x 1 x 1/2	72C80-J-XV	20	40
35908	3 x 1 x 1/2	72C-80-L-V	20	40

Round - Combination Stone

UPC#	SIZE	SPEC.	CARTON	UNIT
35902	4 x 1/2	C150/320-MN7	20	40

Dressing Sticks

UPC#	SIZE	SPEC.	CARTON	UNIT
35909	1 x 1 x 6	C24-S-V	50	100